

GEOTECH

TESTING PTY LTD[®]

ABN 71 076 676 321

TEST RESULTS

DIXON SAND PTY LTD
4610 OLD NORTHERN ROAD
MAROOTA NSW 2756

Laboratory: Penrith
Job No: 7555/1

Project: MATERIAL ANALYSIS
MATERIAL TESTING - 4610 OLD NORTHERN ROAD, MAROOTA

Page 1 of 1

TEST PROCEDURE AS1141.11.1	
Material Description	Dixon Coarse
Sieve Analysis	
Laboratory Number	7555/1-591
Tested By	SB
Checked By	MM
<u>Sieve Size</u>	Percentage Passing
9.5mm	100
4.75mm	99
2.36mm	91
1.18mm	80
600 microns	59
300 microns	19
150 microns	4
75 microns	2
Date Sampled	2-Sep-24
Sampling Procedure	Sampled by Client - Tested as received
Sampling Location	Ex Maroota Quarry
	Pre-treatment Standard Oven Drying
	Washed -

Form No: R024 Version 06 07/21 - issued by ER

Report Date



Nata Accreditation Number 2734
Corporate Site Number 2727

Accredited for compliance with ISO/IEC 17025 - Testing.

M Morley

20-Sep-24

Approved Signatory

34 Borec Road, Penrith NSW 2750
Telephone: (02) 4722 2744

Unit 4, 18-20 Whyalla Place, Prestons NSW 2170
Telephone: (02) 9607 6111

email: info@geotech.com.au www.geotech.com.au